

Solder Cup D-Sub

3778S SERIES





Series options:

A = 4-40 Jack screws assembled on connector

C = Clinch nuts (bottom side)

J = 4-40 Jack screws (bulk packed)

T = Threaded inserts (top side)



Ordering Example:

3778S - 15P - 1C

Positions	A	B	C	D	E
09	16.92	24.99	30.81	16.33	19.28
15	25.25	33.32	39.10	24.66	27.51
25	38.25	47.04	53.10	37.66	41.30
37	55.42	63.50	69.32	54.84	57.71
50	52.86	61.11	66.90	52.34	55.30